PGDP KEVIL DMC MATERIAL TRANSFER FORM



To ensure inclusion in the correct project file, this form MUST be attached to materials being transferred to the DMC. Please fill in all blanks in top of form. Use n/a if not applicable.

Please III III all Dialiks III top of form. Ose fila ii flot appik	aule.	
Document Title.	Document Date:	
Ground water Monitoring Phase III		
ESO P5300	10/8/99	
Document Number.	Page Count:.	
19-32-1 Box 6	n/a	
Author/Organization:	Facility/WAG/SWMU:	
C. J. Winkler Engr. Design + Projec	t Musuusment	
Project Program/Title:	Document Prep. Checklist	
ER	Attached: ☐ Yes ☐ No	
71	Clearance Form: (when required)	
	Attached: ☐ Yes →☐ No	
Keywords/Identifiers/ "Buzz Words"		
1. Monitority Wells 2. Well Installations 3. Specifications		
4. Well + Doring Logs 5. 6.		
	J	
* QA Record: Ves No		
Submitted by: C. J. Winkler Date: 12-8-99 Phone: 462-4557		
*Quality Assurance (QA) Record is a completed document that furnishes evidence of the quality of items and/or		
activities affecting quality.		
PORTION BELOW TO BE COMPLETED BY DMC STAFF		
Comments:		
Comments.		
Publication Data:	Related Documents:	
Status (DC ADE Library), Q	Vital Pagerd: Vac Utta	
Status (RC, ARF, Library): RECG Vital Record: Yes -No		
FG RR PJ/RS U O O ER Item#	0344	
Indexed by:	Date: 12/5/99	
	12/16/199	

CP-20443 (5 5-16-95)



BOX 6

RECORD COPY

	Groundwater Monitoring Phase IV ESO P5300	
	These files are the files held by Engineering Design	
	and Project Management for this project. The project	
:	manager and design from engineering were the same	
	for this majority of this project	
	This box includes design specifications, surveying	
	information, submittals	
	In addition to the above project files this box contains 3	
	expandable folders which contain monitoring well and	,
	boring logs	
	4	